

















Locators

+ 🔍

<input type="checkbox"/>	Name	MAC address	
<input type="checkbox"/>	LR1	AC233FC0BA10-1	 
<input type="checkbox"/>	LR2	AC233FC0BA10-2	 
<input type="checkbox"/>	LR3	AC233FC0BA10-3	 
<input type="checkbox"/>	LR0	AC233FC0BA10-0	 

Locators

+ 🔍

<input type="checkbox"/>	Name	
<input type="checkbox"/>	LR1	 
<input type="checkbox"/>	LR2	 
<input type="checkbox"/>	LR3	 
<input type="checkbox"/>	LR0	 

Add locator

Name *
LR5

MAC address *
AC233FC0BA10-1

Manufacturer *
Minew

Model *
AR1

Area
Warehouse

x*
0.234

y*
0.345

z*
2.599

Add Cancel

Areas + 🔍

<input type="checkbox"/>	Name		
<input type="checkbox"/>	Warehouse		

PrecisionRTLS™ Logout

Areas + 🔍

Add area ✕

Name*
Office

x*
5.04

y*
4.06


z*
2.67

Area plan/map image

No image selected

Drop an image or click to select a file to upload. ✕

Add Cancel



Alert rules

<input type="checkbox"/>	Name ↑	Alert condition	Beacons	Area	Zones	Send email	
<input type="checkbox"/>	Gone	Has disappeared	Filtered	Any	Any	<input type="checkbox"/>	...
<input type="checkbox"/>	Leaving	Has exited Zone(s)	Any	Any	Left	<input type="checkbox"/>	...
<input type="checkbox"/>	Test	Has entered Zone(s)	Any	Any	test	<input type="checkbox"/>	...

Page: 1 Rows per page: 10 1 - 3 of 3 < >

